



The gaskets supplied by OLMAR can withstand a maximum of 2 cycles. After the second cycle the material is completely degraded and falls apart in the hands. Use of these gaskets for more than 2 cycles is DANGEROUS from a safety point of view. OLMAR is required to react immediately to find out solution.

Los problemas anteriormente descritos fueron revisados, discutidos y acordados con los representantes de OLMAR. No obstante, se han negado a firmar el protocolo actual y abandonaron la fábrica a las 14.10 sin abrir los autoclaves 1 y 2.

The problems described above were reviewed, discussed and agreed with OLMAR representatives. However, they have refused to sign the current protocol and left the factory at 14.10 without open autoclaves #1 and #2.

<p>Baublock Alexander Babasin</p> 	<p>Baublock David Santamaría</p> 	<p>Olmar</p>	<p>27/09/2024 14 de 14</p>
---	--	--------------	--